

AHERA REINSPECTION
The Elementary School (Building B)
at
300 Park Street
Gaston, Oregon 97119

Prepared For:

Brian Van Dyke, Facilities
Gaston School District SD 511J
300 Park Street
Gaston, Oregon 97119

EIS Job No. 2021002. Gaston Elementary School

Prepared By:

Charles A. Spear
AHERA Certification #IRO-21-2439A
Environmental Inspection Services
11981 Fargo Road
Aurora, Oregon 97002
(503) 680-6398
E MAIL: charles_a_spear@yahoo.com



Charles A. Spear, Partner

March 16, 2021



EIS
ENVIRONMENTAL INSPECTION SERVICES



TABLE OF CONTENTS

<u>DESCRIPTION</u>	<u>PAGE NO</u>
EXECUTIVE SUMMARY.....	1-4
ACCREDITATION / RESUME.....	5-8
REGULATIONS (BACKGROUND).....	9-11
ACTIVITY (BACKGROUND).....	12
REINSPECTION REPORT.....	13
REINSPECTION SCOPE OF WORK.....	13
SUMMARY OF FRIABLE / NONFRIABLE ACBM	14-16
RECOMMENDATIONS AND CONCLUSIONS.....	16-17
LIMITATIONS.....	17

APPENDIX 1.0

SITE PLAN

APPENDIX 2.0

RECORDING FORMS FOR ASSESSMENT DATA

APPENDIX 3.0

REGULATIONS

March 16, 2021

EIS JOB No. 2021002.Gaston Elementary School (Building B)

Brian Van Dyke, Facilities
Gaston School District SD 511J
300 Park Street
Gaston, Oregon 97119

RE: Asbestos 2021 AHERA 3-year Reinspection of the Gaston
Elementary School (Building B) located at 300 Park Street in
Gaston, Oregon

Dear Mr. Brian Van Dyke,

The Federal Asbestos Hazard Emergency Response Act (commonly referred to as AHERA) was signed into law in 1986. AHERA requires both private and public non-profit primary and secondary schools to inspect all buildings that are leased, owned, or otherwise used as school buildings for the presence of asbestos-containing building materials (ACBM). The U.S. Environmental Protection Agency (EPA) published regulations and enforces AHERA.

EIS is pleased to present the March, 2021 AHERA reinspection for The Gaston Elementary School (Building B) located at 300 Park Street in Gaston, Oregon. The subject Elementary school has been partially remodeled and renovated. Suspect asbestos-containing building materials (ACBM) includes on-foot tan tile, wall plaster/textures, moulding mastic adhesives, one foot pink tiles, acoustic ceiling panels, 9" tan pattern tiles, tan pattern linoleum, and 1' tan pattern tiles. No problematic asbestos containing building materials conditions were observed in the school.

The subject original functional spaces were examined throughout for the presence of confirmed and suspect asbestos-containing building materials (ACBM). All representative functional spaces and relative homogeneous sampling areas were examined during the inspection process.

A total of twenty (20) data sheets were completed for the school and no noteworthy wear and debris considerations were noted for the subject building materials. The sheets summarize the accessibility and condition of identified confirmed and/or suspect asbestos-containing building materials (ACBM) observed throughout the original Gaston Elementary School building.

All identified ACBM are candidate materials for in-place operations and maintenance and asbestos abatement is not recommended or required. The condition of the existing suspect ACBM in the school is good to excellent and considered to be protective of student safety and health. No bulk samples were collected from suspect asbestos-containing building materials (ACBM).

THERMAL SYSTEM INSULATION (TSI)

No Thermal system insulation (TSI) was observed during this inspection.

RESILIENT FLOOR COVERINGS

(VINYL FLOOR TILE & SHEET FLOOR LINOLEUM)

Varieties of suspect resilient floor coverings include nine inch tan pattern tile, one foot pattern tiles, one foot pink tiles and tan pattern linoleum.

No samples were collected from vinyl floor tile and linoleum materials. Refer to data sheet No.s 1,3,7,11,16,3A,2A, and 12 for vinyl tile additional details. All examined floor coverings were observed in the restrooms, hallways and classrooms and were noted in good to excellent condition, well maintained, accessible, and intact. No significant floor covering condition or damage concerns were noted. Minor damaged floor tiles may be replaced as a repair item.

COVE-BASE ADHESIVE

Cove-base mastic adhesive was observed on floor moulding within various functional spaces throughout the subject Elementary school to include the kitchen, gymnasium, and classrooms. The moulding is intact and in good condition. No samples were collected in moulding mastics. (Refer to data sheets No.s 6.8.,10, and 13 for details.

TAPE JOINT COMPOUND

Tape joint compound was noted throughout the Elementary school wall surfaces in areas of sheet rock joints. This compound is typically applied to taped joints applied between sheet rock wall surfaces. Tape joint compound exists on sheet rock panels throughout the subject building. The compound usage was extensive and is likely throughout the entire structure original pre-1980 wall panel tape joints. The compound is in good condition, sealed and or encapsulated, and a candidate building material for operations and maintenance.

ACOUSTIC CEILING TILES

Acoustic ceiling tiles were observed in good condition. No ceiling tile concerns were noted. Refer to sheet No.s 2,4,9,14 and 17 for reference.

PLASTER (SKIM COAT)


Original wall surfaces have plaster skim coat applications observed within functional areas of the building. No samples were collected. EIS noted no plaster concerns. Refer to data sheet No.s 5 for details. The wall plaster surfaces were noted to be in good condition and candidate building materials for in-place operations and maintenance. The existing plaster surfaces are sealed and coated in latex paint applications and considered to be in good condition. No concerns were noted.

All suspect and previously analytically confirmed ACBM were noted to be in good to excellent condition. All ACBM are considered candidate building materials for operations and maintenance in accordance with the standard O&M recommendations stated in The AHERA Management Plan and the EPA Manual known as Managing Asbestos in Place - A Builder Owners Guide to Operations and Maintenance Programs for Asbestos-Containing Materials per EPA Manual No. 20T 2003 dated July, 1990.

Candidate ACBM include skim coat applications on wall surfaces, acoustic ceiling tiles, ceiling tile mastics, moulding mastic adhesive, and vinyl flooring and vinyl tiles. No asbestos containing debris or other related asbestos material concerns were noted at the aforementioned building. No asbestos containing debris, damaged and disturbed ACBM or other related asbestos material concerns were noted at the aforementioned materials. Asbestos-containing thermal system insulation piperuns were observed in the building. Asbestos abatement is not recommended or necessary at this time.

Thank you for the opportunity to perform the March, 2021 asbestos reinspection. Progress has been made since the AHERA Management Plan issuance and initial inspections. The Gaston Elementary School has been partially remodeled, relatively modern, and remaining plaster skim coats and original VAT and ceiling tile materials are well maintained and no asbestos material safety concerns were noted in the school. If there are any questions feel free to contact us at (503) 680-6398.

Respectfully,


Charles A. Spear

Partner

AHERA Inspector IRO-21-2439A

This reinspection of the Gaston Elementary School Building and common building was performed on Friday, February 26, 2021 by Charles A. Spear. AHERA Inspector Certification No. IRO-21-2439A. The AHERA Inspector expiration date is February, 2022. All inspection / assessment activities were performed in accordance with the reinspection requirements of Part III 40 CFR Part 763. Asbestos-Containing Materials in Schools; Final Rule and Notice.

RESUME

**CHARLES ARTHUR SPEAR
REGISTERED ENVIRONMENTAL ASSESSOR
REA - 01241**

AHERA INSPECTOR (EPA CERTIFICATION NO. IRO-21-2439A)

**CERTIFIED ENVIRONMENTAL INSPECTOR
CEI - 10364**

Professional Background

Charles A. Spear, President and founder of Environmental Inspection Services has over 20 years technical experience ranging from facility food technologist to hazardous waste site remediation at Federal SUPERFUND sites from California to Maryland. Mr. Spear has successfully performed over 3,000 Phase One, Phase Two, and Phase Three Environmental Site Assessment inspections on properties from California to Alaska and east to Maryland. Mr. Spear has managed such projects as spilled mustard gas and organophosphate remediation as a sergeant of the U.S. Army Chemical Corps Technical Escort Unit Drill & Transfer Unit at Umatilla Army Depot and removal of leaking solvent underground storage tanks in California and Oregon.

Specifically, Mr. Spear has worked with clients such as: the International Fabric Care Industry (IFI), the U.S. Environmental Protection Agency, The U.S. Department of Defense, The Oregon Department of Environmental Quality (ODEQ), The Oregon Department of Forestry, INTEL, Sun Microsystems, IBM, Rohm & Haas, General Electric, AT&T, Texaco, Unocal, BP, Lockheed Missile and Space Center, FMC Corporation, Oregon Department of Fish & Wildlife, Washington Department of Fish & Wildlife, City of Beaverton, City of Hillsboro, City of Corvallis, Housing Authority of Portland, Northwest Oregon Housing Authority, Washington County Department of Housing, Housing & Urban Development, numerous lenders and mortgage companies, many private development and site remedial site projects, and many attorneys and investors.

Mr. Spear managed complex tank farm removals at Xidex Corporation in Sunnyvale, California and was the site cleanup manager at the Rose City Plating Site currently developed as the Oregon Convention Center. Mr. Spear is a certified hazardous waste professional who has coupled military experience as a Nuclear, Biological and Chemical Specialist (U.S. Army MOS 54E20) with experience as a professional research engineer in both the corrugated paper and petroleum industries.

Mr. Spear has managed food industry quality control as an inplant food technologist and prepared cost reduction programs as a corrugated box board industrial engineer in Dallas, Texas. He is currently registered with the states of California, Washington, and Oregon and is an active member of the national respected Environmental Assessment Association. Due diligence projects have been performed throughout the United States from FairGaston, Alaska to San Diego, California.

Professional experience includes the following:

Professional Experience

- * Dry Cleaner Inspections
- * Environmental Consultation
- * Waste Reduction Audits
- * Regulatory Compliance Audits
- * Drum Yard Clearances
- * Tank Farm Removals/Replacements
- * Lab Packaging & Supervision
- * Environmental Site Assessments
- * Superfund Site Remediation
- * Hazardous Waste site Project Design & Management
- * Habitat/Wetlands Restoration
- * AHERA asbestos inspections for school districts
- * Landfill Remediation
- * Agricultural assessments
- * Indoor air quality inspections

Professional Employment/Consultation

- * C.F.S. Continental Coffee, Inc., Food technologist, Chicago, Illinois
- * Holiday Industries, Research Engineer, Grand Prairie, Texas
- * Alton Packaging Corporation, Industrial Engineer, Dallas, Texas
- * U.S. Army Chemical Corps., Nuclear, Biological, Chemical Specialist - Special assignment - Umatilla Army Depot (DATS)
- * U.S. Army Chemical Corps. Technical Escort Unit in Edgewood, Maryland
- * Rollins Environmental Services, Remedial Project Manager
- * Crown Environmental Services, Technical Director, Redmond, California
- * Dames & Moore, Design Engineer, Portland, Oregon
- * Pegasus Environmental Management Services, Director of Technical Services
- * Pacific Tank & Construction, Manager of Estimation, Portland, Oregon
- * Enviro-Logic Inc., Director of Environmental Site Assessment Division
- * Environmental Inspection Services Inc., Founder/President

Professional Education

- * Bachelor of Science, Chemistry, Northeastern Illinois University, 1978
- * U.S. Army Chemical School, Ft. McClellan, Alabama, 1983
- * U.S. Army Technical Escort Unit, Accident/Incident Response Training Center 1983
- * Registered Environmental Assessor REA - 01241
- * Certified Environmental Inspector CEI - 10364
- * AHERA Certified Asbestos Inspector IR-16-2439A
- * ODEQ Soil Matrix Assessor & UST Decommission Supervisor
- * Washington DOE Registered Environmental Assessor
- * Wetland Specialist - Training Wetlands Institute 1997
- * EPA/HUD Lead-Based Paint (LBP) Inspector & Risk Assessor
- * ASTM Certification Training, May, 2004

Additional Education

- * Joint Military Material Packaging & Transportation
- * Asbestos Abatement Seminar attendance 1987
- * Thin Layer Chromatography, 1989
- * Oregon Registered Underground storage Tank Supervisor, 1998
- * Oregon Registered Soil Matrix Assessor, 1998
- * Washington Registered Assessor, 1991
- * Washington Registered Underground Storage Tank Supervisor, 1991
- * Wetland Training Institute Delineation Course Study University of Portland March 1997
- * 40-Hour HAZMAT Certified
- * AHERA-Certified Inspector

Special Skills

- * Facility Environmental Compliance Audits
- * ASTM standard Environmental Site Assessments
- * Computer Programming
- * Organic surfactant chemical synthesis and analysis
- * Hazardous Waste Site remediation/ estimating/ standards development
- * Design of filtration systems, batch and continuous process optimization studies
- * QA/QC Procedures
- * SUPERFUND Site Management
- * Industrial/ Research Engineering
- * Hazardous Waste Site Remediation/ Consultation
- * Wetlands Delineation and Habitat Restoration

Certification

- * U.S. Army MOS 54E20 - U.S. Army Chemical Corps.
- * International Fire Code Institute (IFCI) Certified UST Supervisor
- * International Fire Code Institute (IFCI) Certified Soil Matrix Assessor
- * Certified Hazardous Waste Manager
- * 40-hour OSHA Training
- * 40-hour OSHA Supervisor Training
- * Registered Environmental Assessor (DOE)
- * DEQ Registered UST Supervisor
- * DEQ Registered Soil Matrix Assessor
- * Resolution Trust Corporation (RTC) approved Environmental Assessor
- * California Registered Environmental Assessor (REA-01241) - discontinued
- * Department of Ecology (DOE) Registered Environmental Assessor
- * Environmental Assessment Association, Certified Environmental Inspector & Transaction Specialist (CEI-10364)
- * AHERA Certified Asbestos Inspector
- * Wetland Delineator Graduate Wetland Training Institute, University of Portland 1997
- * EPA/HUD LBP Inspector & Risk Assessor
- * ASTM certification

REGULATIONS

Asbestos - Background

Asbestos is generally referred to as six naturally occurring fibrous minerals found in certain types of rock formations. The minerals Chrysotile, Amosite, and Crocidolite have been most commonly utilized in building materials. Asbestos is typically separated into very thin fibers. Asbestos is strong, incombustible, and corrosion resistant and was utilized early in the century into the 1970's. Asbestos may cause substantial health problems when it is inhaled in sufficient quantities.

Asbestos is considered to be a hazardous air contaminant and a known human carcinogen. Once used extensively as an insulation material, asbestos has been banned from most construction and manufacturing since the mid-1970's. The most dangerous forms of asbestos are those materials containing asbestos which can be easily crushed or crumbled known as "friable asbestos". Friable asbestos is dangerous since asbestos fibers can be easily released into the air. Such activities as remodeling and demolition projects are likely to disturb asbestos. If asbestos-containing building materials (ACBM) are not handled properly then these types of projects can pose as a serious threat to workers and the general public.

Regulatory Background

In 1986, Congress enacted the Asbestos Hazard Emergency Response Act (AHERA or TSCA Title II) which mandated a regulatory program to address asbestos hazards in schools. A copy of the Environmental Protection Agency Asbestos Model Accreditation Plan interim Final Rule (59FR2236-5260) is enclosed for reference. President Reagan signed into law the Asbestos Hazard Emergency Response Act (AHERA) on October 22, 1986. This law enacted, among other provisions, Title 2 of the Toxic Substances control Act (TSCA) 15 U.S.C. Section 2641 through 2654; Section 203 of Title II, 15 U.S.C. 2643. Copies of AHERA 40 CFR Part 763 are enclosed for reference.

AHERA requires the following:

- (1.0) - Perform an original inspection and periodic re-inspections every three years for asbestos containing material;
- (2.0) - Develop, maintain, and update an asbestos management plan. A copy must be kept in the school building, as well as in the districts administrative office;
- (3.0) - Provide an annual written notification to parent, teacher, and employee organizations regarding the availability of the school's asbestos management plan for review and any asbestos abatement actions taken or planned in the school;
- (4.0) - Designate a contact person (also known as the asbestos designee) to ensure the responsibilities of the local education agency are properly implemented. Details on the asbestos designee's responsibilities may be found at : www.epa.gov/region02/ahera/ampauditchecklist.pdf
- (5.0) - Perform a periodic visual surveillance every six months of all known or suspected asbestos-containing building material;
- (6.0) - Provide custodial staff with asbestos hazard awareness training

Note: If a building has never been inspected for asbestos, a new AHERA inspection must be completed as soon as possible. Pursuant to AHERA Section 763.85(a), any building leased or acquired on or after October 12, 1988, that is used as a school building shall be inspected for asbestos prior to use as a school building. In the event that the emergency use of an uninspected building as a school building is necessitated, such building must be inspected for asbestos within 30 days after the commencement of such use.

Section 112 of the Clean Air Act (CAA) requires EPA to develop emission standards for hazardous air pollutants. In response to this section the EPA published a list of hazardous air pollutants and promulgated the National Emission Standards for Hazardous Air Pollutants (NESHAP) regulations.

The asbestos NESHAP (40 CFR 61, Subpart M) addresses milling, manufacturing and fabricating operations, demolition, and renovation activities, waste disposal issues, active and inactive waste disposal sites and asbestos conversion processes.

In the initial Asbestos NESHAP rule promulgated in 1973, a distinction was made between building materials that would readily release asbestos fibers when damaged or disturbed and those materials that were unlikely to result in significant fiber release. The terms "friable and non-friable" were used to make this distinction. EPA has since determined that, if severely damaged, or otherwise non-friable materials can release significant amounts of asbestos fibers.

Friable asbestos-containing material (ACM) is defined by the Asbestos NESHAP as any material containing more than one percent (1%) asbestos as determined using the method specified in Appendix A, Subpart F, 40 CFR Part 763, Section 1, Polarized Light Microscopy (PLM), that when dry, can be crumbled, pulverized, or reduced to powder by hand pressure (section 61.141). Non-friable material is ACM not reduced to powder by similar circumstances.

ACTIVITY

Background

It is the responsibility and primary mission of the AHERA inspector to determine whether ACBM is present in a building and to assess the physical characteristics of the ACBM in the structure. The inspection process includes an investigation of available records; an inspection of the functional spaces; an assessment of the condition of observed ACBM; reviews of available architectural and as built plans; review of work change orders; examination of material specifications indicating the presence of ACBM; examination of friable and non-friable ACBM; delineation of homogenous sample areas; collection of samples; and information on ACBM conditions.

The Gaston Elementary School gymnasium, kitchen, cafeteria, classrooms, library, offices, galleries, vestibules, and hallways were examined for suspect ACBM during the AHERA reinspection. Data forms were completed. The completed forms were edited for completeness and potential problem areas or areas requiring abatement or extensive repair were noted. Copies of the forms are attached for review and reference and generally represent a condition evaluation and summary of the potential homogeneous sampling areas and functional space areas. No concerns were noted regarding all examined ACBM.

REINSPECTION

Charles A. Spear conducted a triennial asbestos reinspection of the Gaston Elementary School building on Friday, February 26, 2021. Actual field activities included blueprint and/or facility floor plan review; an interview with the maintenance supervisor; and a physical reinspection examination of all suspect and confirmed friable and non-friable asbestos-containing building materials at the subject Gaston school. The Gaston School hallways, common rooms, and class rooms wall, floor and ceiling surfaces are well maintained.

The accredited EIS inspector performed a preliminary examination of the subject structure. The AHERA inspector confirmed the existence of suspect asbestos-containing building materials (ACBM) such as vinyl asbestos floor tiles; vinyl linoleum flooring, moulding mastic adhesives; skim coat plaster applications on sheet rock; and acoustic ceiling tiles ceiling tile adhesives, and miscellaneous and cementitious materials.

All accessible areas to include The Gaston School gymnasium, hallways, classrooms, offices, cafeteria, boiler room, girls and boys locker rooms, original kitchen, shops, vestibules, and storage rooms and stairwells were examined for suspect ACBM during the AHERA reinspection. All the aforementioned functional areas were visibly inspected during this AHERA reinspection. No significantly damaged ACBM was observed during these inspections.

The Gaston Elementary School Building walkover revealed all asbestos-containing materials to be candidate building materials for Operations and Maintenance. The original AHERA Management Plan confirmed asbestos in several forms. Operations and Maintenance is recommended for all confirmed and suspected asbestos-containing materials to include vinyl asbestos tiles (VAT); ceiling tiles; and miscellaneous materials. No ACBM concerns were noted for the aforementioned materials. Asbestos abatement is not recommended for the subject facility ACBM at this time. Minor repair of damaged areas is adequate and protective.

All the aforementioned materials are in good condition and candidate materials for Operations and Maintenance. No noteworthy damages or disturbances of ACBM were observed. These materials have low potential for damage with no influence of vibration or potential for air erosion.

SUMMARY OF FRIABLE / NONFRIABLE ACBM

Staff and maintenance personnel are encouraged to consult the forms prior to maintenance activities planned for suspect ACBM.

1.0 Vinyl Asbestos Tile (VAT) Non-Friable

Varieties of suspect resilient floor coverings to include tan pattern floor linoleum, nine-inch tan pattern tile, one foot tan pattern tiles, one foot pink floor tiles, and one foot white/grey floor tile in the hallways and classrooms. No samples were collected from vinyl floor tile. (Refer to data sheet No.s 1,3,7,11,16,2a and 3A for details).

Description - a nonfriable vinyl material with vinyl filler and binder. An adhesive mastic is utilized to adhere to the vinyl floor surfacing to another substrate. The VAT asbestos content is described as a separate matrix from the adhesive mastic. VAT subject to removal must be removed in whole pieces by using the proper tools with wetting and proper handling, wrapping and disposal procedures. No poor condition floor coverings were noted.

AHERA Classification-Miscellaneous

COVE-BASE ADHESIVE

Cove-base mastic adhesive was observed on floor moulding within various functional spaces throughout the subject Elementary school to include the hallways, kitchen, gymnasium, and classrooms. Very minor edge wear was noted. The moulding is intact and in good condition. No samples were collected in moulding mastics. No samples were collected in moulding mastics. (Refer to data sheets No.s 6,8,10,13 for details).

TAPE JOINT COMPOUND

Tape joint compound was noted throughout the Elementary school wall surfaces in areas of sheet rock joints. This compound is typically applied to taped joints applied between sheet rock wall surfaces. Tape joint compound exists on sheet rock panels throughout the subject building. The compound usage was extensive and is likely throughout the entire structure original pre-1980 wall panel tape joints. The compound is in good condition, sealed and or encapsulated, and a candidate building material for operations and maintenance.

Products not utilized as TSI or surfacing materials are classified as miscellaneous materials. Materials such as transite pipe, ceiling tiles, fire doors, gaskets, vinyl floor coverings, duct work flexible connections, roofing felt, roofing flashing, and fume hood ducting and paneling are miscellaneous materials. These miscellaneous materials were noted in various areas of the subject building as noted in data sheets. Samples were not collected from suspect ACBM.

ACM sprayed or troweled onto surfaces for acoustical, decorative, or fireproofing purposes. Asbestos is blended in to spray-applied and troweled-on products to include structural fireproofing, stucco, plaster, acoustical and decorative surfaces, and joint compounds.

2.0 Thermal System Insulation (TSI)

AHERA Classification - TSI

No TSI was observed at this time.

Insulation used on mechanical systems to prevent heat ,loss or gain and condensation. Steam and hot water lines, boiler tanks, expansion joints, fittings and other mechanical systems are commonly insulated with pre-fabricated asbestos-containing magnesium silicate. The material is typically white in color and is encased in a plaster-impregnated canvas wrapping. Asbestos containing mud compounds are often used on elbows, valves, identification plates, miscellaneous fittings, and for other special applications on mechanical systems.

3.0 Acoustic ceiling Tiles, Suspect - Non Friable Miscellaneous

No problematic ceiling tiles were observed on ceiling surfaces throughout the building. No problematic ceiling tiles were observed on ceiling surfaces throughout the building. Fibrous acoustical ceiling tiles, varying in size from one foot square to two by four foot lengths. Fibrous material integrated with cellulose binder and directly adhered to ceiling surfaces. The material in most classrooms is in good condition. Ceiling tiles are easily damaged and may create a dust hazard if the material is broken, abraded, cut, or drilled. Acoustical ceiling tiles were observed on ceiling surfaces in the classrooms. The adhesive tabs to the tiles are suspect ACBM and are candidate building materials for in-place operations and maintenance. No ceiling tile or mastic concerns were noted. Refer to Sheet No.s 2,4,9,14, and 17 for details.

4.0 Adhesive mastic

Cove-base mastic adhesive was observed on floor moulding within various functional spaces throughout the subject Elementary school to include the kitchen, gymnasium, classrooms, and annex buildings. Edge wear was noted in the kitchen, annex room No. 24, and other minor areas in the building. The moulding is otherwise intact and in good condition. No samples were collected in moulding mastics. (Refer to data sheet No.s 6,8,10 and 13 for details.

Typical to adhere ceiling acoustic panels to underlying substrate. Material is non-problematic and non-friable.

ACM sprayed or troweled onto surfaces for acoustical, decorative, or fireproofing purposes. Asbestos is blended in to spray-applied and troweled-on products to include structural fireproofing, stucco, plaster, acoustical and decorative surfaces, and joint compounds.

(5.0) - Sprayed-on acoustic popcorn ceiling materials

No popcorn ceiling materials were observed within the building. Popcorn ceiling materials are an acoustic sprayed-on application spray applied to ceiling sheet rock surfaces as an acoustic material.

RECOMMENDATIONS AND CONCLUSIONS

All vinly linleum floor surfaces, vinyl asbestos tiles flooring materials; acoustic ceiling tiles; ceiling tile mastics; moulding mastic adhesives, and miscellaneous skim coat plaster applications on sheet rock wall panels materials are candidate building materials for Operations and Maintenance. Asbestos abatement of confirmed asbestos-containing building materials is not recommended at this time.

In all areas where work or work-related activities are planned materials must be properly tested and classified as non-asbestos. If confirmed, all asbestos containing building materials must be handled, managed, or removed in accordance with state and federal regulations. Asbestos abatement is not recommended or required at this time. No environmental concerns regarding ACM at the Gaston School were noted at this time.

All confirmed ACBM scheduled for material damage or disturbance by renovation, remodeling, or demolition must be properly abated in accordance with EPA and ODEQ recommendations and procedures.

All maintenance workers and related staff must handle ACBM in accordance with the protective provisions of the Oregon Occupational Safety and Health Administration (OSHA) requirements. Maintenance and staff personnel are encouraged to follow the management recommendations of the AHERA management plan and related operations and maintenance procedures as outlined in the appendix of this letter.

LIMITATIONS


This report was prepared in accordance with generally accepted AHERA standards of environmental reinspection practice at the time this investigation was performed. Evaluations of the conditions at the site for the purpose of this investigation are made from a limited number of observation points and may be subjective in some cases. The subject school district is solely responsible for providing any notices or disclosures to concerned public agencies or to the public.

Environmental Inspection Services has prepared this report based on information collected from available records and files. The scope of this investigation is limited and did not include subsurface exploration or chemical screening of soil and groundwater beneath the site. No bulk material samples were collected from the subject school suspect ACBM for the purposes of this reinspection.


The findings and conclusions are not to be regarded as scientific certainties. Findings are based on professional judgement concerning data significance. Evaluation of the presence of asbestos-containing building materials in the subject school is based upon actual analytical test results, EIS gathered data initially furnished in previous reinspection and the site specific AHERA Management Plans prepared by others. This report is an expression of professional opinion and is not a warranty express or implied.

APPENDIX 1.0

SITE PLAN



Gaston (Elementary) Evacuation Routes



Front Playground SECONDARY ASSEMBLY AREA

APPENDIX 2.0

RECORDING FORMS FOR ASSESSMENT DATA

RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING gastown e/h FLOOR 1st
 FUNCTIONAL AREA class. rm HOMOGENEOUS MATERIAL tan pat molen
 TYPE OF SUSPECT MATERIAL SURFACING _____ TSI _____
 FLOORING X CEILING _____ WALLS _____ OTHER _____
 DESCRIPTION OF MATERIAL _____
 APPROXIMATE AMOUNT OF MATERIAL (SF) 405 (LF) _____

REINSPECTION DATA :

ACBM TYPE: SURFACING _____ TSI _____ MISC _____ FLOOR X CEILING _____

DESCRIPTION

APPROXIMATE AMOUNT OF MATERIAL (SF) 405 (LF) _____
 FRIABLE: _____ (YES) X (NO) _____
 NON-FRIABLE _____ (YES) _____ (NO) X
 WARNING LABELS _____ (YES) _____ (NO) X
 CHANGE FROM INITIAL AHERA REPORT _____ (YES) _____ (NO) X

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION _____ PHYSICAL X WATER _____ FIRE _____
 EXTENT OF DAMAGE: LOCALIZED _____ DISTRIBUTED X
 PERCENT OF DAMAGE: 0% _____ 1-10% X 10-25% _____ 25-100% _____
 OVERALL RATING: GOOD X FAIR _____ POOR _____
 DESCRIPTION: _____

POTENTIAL FOR DISTURBANCE: ACCESSIBLE X INACCESSIBLE _____
 POTENTIAL FOR CONTACT: _____ HIGH _____ MODERATE _____ LOW X
 INFLUENCE OF VIBRATION: _____ HIGH _____ MODERATE _____ LOW X
 POTENTIAL FOR AIR EROSION: _____ HIGH _____ MODERATE _____ LOW X
 OVERALL RATING: _____ HIGH _____ MODERATE _____ LOW _____
 DESCRIPTION Open

LOCATION IN AIR PLENUM: YES X NO _____
 COMMENTS Open

INSPECTOR: Charles Spear ACCREDITATION NO. IDA-21-24394
 SIGNATURE: Charles Sr DATE: 2/26/21 For

RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING Gaston Bldg FLOOR MAIN
 FUNCTIONAL AREA common HOMOGENEOUS MATERIAL ac cels panels
 TYPE OF SUSPECT MATERIAL SURFACING TSI
 FLOORING CEILING X WALLS OTHER
 DESCRIPTION OF MATERIAL 4 by 8 cels panels
 APPROXIMATE AMOUNT OF MATERIAL (SF) 100 (LF)

REINSPECTION DATA :

ACBM TYPE: SURFACING TSI MISC FLOOR CEILING X

DESCRIPTION

4 by 8 cels panels
 APPROXIMATE AMOUNT OF MATERIAL (SF) 400 (LF)
 FRIABLE: (YES) X (NO)
 NON-FRIABLE (YES) (NO) X
 WARNING LABELS (YES) (NO) X
 CHANGE FROM INITIAL AHERA REPORT (YES) (NO) X

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION PHYSICAL X WATER FIRE
 EXTENT OF DAMAGE: LOCALIZED DISTRIBUTED X
 PERCENT OF DAMAGE: 0% 1-10% X 10-25% 25-100%
 OVERALL RATING: GOOD X FAIR POOR
 DESCRIPTION:

POTENTIAL FOR DISTURBANCE: ACCESSIBLE X INACCESSIBLE
 POTENTIAL FOR CONTACT: HIGH MODERATE LOW X
 INFLUENCE OF VIBRATION: HIGH MODERATE LOW X
 POTENTIAL FOR AIR EROSION: HIGH MODERATE LOW X
 OVERALL RATING: HIGH MODERATE LOW
 DESCRIPTION OK

LOCATION IN AIR PLENUM: YES X NO
 COMMENTS OK

INSPECTOR: Charles Spear
 SIGNATURE: Charles Spear

ACCREDITATION NO. IDA21-2439A
 DATE: 2/26/21 TSR

RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING garage 315 FLOOR Men
 FUNCTIONAL AREA hallways HOMOGENEOUS MATERIAL 9" fiber post VMT
 TYPE OF SUSPECT MATERIAL SURFACING TSI
 FLOORING + CEILING WALLS OTHER +
 DESCRIPTION OF MATERIAL 9" fiber post VMT

APPROXIMATE AMOUNT OF MATERIAL (SF) 10 Kt (LF)

REINSPECTION DATA :

ACBM TYPE: SURFACING TSI MISC FLOOR Y CEILING

DESCRIPTION

APPROXIMATE AMOUNT OF MATERIAL (SF) 10 Kt (LF)
 FRIABLE: (YES) Y (NO)
 NON-FRIABLE (YES) (NO) X
 WARNING LABELS (YES) (NO) X
 CHANGE FROM INITIAL AHERA REPORT (YES) (NO) Y

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION PHYSICAL Y WATER FIRE
 EXTENT OF DAMAGE: LOCALIZED DISTRIBUTED X
 PERCENT OF DAMAGE: 0% 1-10% Y 10-25% 25-100%
 OVERALL RATING: GOOD Y FAIR POOR
 DESCRIPTION:

POTENTIAL FOR DISTURBANCE: ACCESSIBLE Y INACCESSIBLE
 POTENTIAL FOR CONTACT: HIGH MODERATE Y LOW
 INFLUENCE OF VIBRATION: Y HIGH MODERATE LOW
 POTENTIAL FOR AIR EROSION: HIGH MODERATE LOW X
 OVERALL RATING: HIGH MODERATE LOW Y
 DESCRIPTION Ok

LOCATION IN AIR PLENUM: YES Y NO
 COMMENTS Ok

INSPECTOR: Charles Spear ACCREDITATION NO. ILD-21-2439A
 SIGNATURE: Charles Spear DATE: 2/26/21 - PM

RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING gaston B6 FLOOR man
 FUNCTIONAL AREA dagrm HOMOGENEOUS MATERIAL calm 190 cm 46
 TYPE OF SUSPECT MATERIAL SURFACING TSI
 FLOORING CEILING X WALLS OTHER
 DESCRIPTION OF MATERIAL

APPROXIMATE AMOUNT OF MATERIAL (SF) 1 X 20 (LF)

REINSPECTION DATA :

ACBM TYPE: SURFACING TSI MISC FLOOR CEILING X

DESCRIPTION

1 acc ceiling tiles
 APPROXIMATE AMOUNT OF MATERIAL (SF) 116 (LF)
 FRIABLE: (YES) (NO) X
 NON-FRIABLE (YES) (NO) X
 WARNING LABELS (YES) (NO) X
 CHANGE FROM INITIAL AHERA REPORT (YES) (NO)

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION PHYSICAL X WATER FIRE
 EXTENT OF DAMAGE: LOCALIZED DISTRIBUTED X
 PERCENT OF DAMAGE: 0% 1-10% X 10-25% 25-100%
 OVERALL RATING: GOOD FAIR POOR
 DESCRIPTION: intact

POTENTIAL FOR DISTURBANCE: ACCESSIBLE X INACCESSIBLE
 POTENTIAL FOR CONTACT: HIGH MODERATE LOW X
 INFLUENCE OF VIBRATION: HIGH MODERATE LOW X
 POTENTIAL FOR AIR EROSION: HIGH MODERATE LOW X
 OVERALL RATING: HIGH MODERATE LOW X
 DESCRIPTION okm

LOCATION IN AIR PLENUM: YES X NO
 COMMENTS okm

INSPECTOR: Charles Spear ACCREDITATION NO. EAD-24-2439A
 SIGNATURE: Charles Spear DATE: 2/26/21 - P

RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING gaston bls FLOOR main
 FUNCTIONAL AREA classroom HOMOGENEOUS MATERIAL plaster
 TYPE OF SUSPECT MATERIAL SURFACING X TSI _____
 FLOORING _____ CEILING _____ WALLS _____ OTHER _____
 DESCRIPTION OF MATERIAL texture patch

APPROXIMATE AMOUNT OF MATERIAL (SF) 50 (LF) _____

REINSPECTION DATA :

ACBM TYPE: SURFACING X TSI _____ MISC _____ FLOOR _____ CEILING _____

DESCRIPTION

texture
 APPROXIMATE AMOUNT OF MATERIAL (SF) 50 (LF) _____
 FRIABLE: _____ (YES) X (NO) _____
 NON-FRIABLE _____ (YES) _____ (NO) X
 WARNING LABELS _____ (YES) _____ (NO) X
 CHANGE FROM INITIAL AHERA REPORT _____ (YES) _____ (NO) X

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION _____ PHYSICAL X WATER _____ FIRE _____
 EXTENT OF DAMAGE: LOCALIZED _____ DISTRIBUTED X
 PERCENT OF DAMAGE: 0% _____ 1-10% X 10-25% _____ 25-100% _____
 OVERALL RATING: GOOD X FAIR _____ POOR _____
 DESCRIPTION: _____

POTENTIAL FOR DISTURBANCE:	ACCESSIBLE <u>X</u>	INACCESSIBLE _____
POTENTIAL FOR CONTACT:	HIGH _____	MODERATE _____ LOW <u>X</u>
INFLUENCE OF VIBRATION:	HIGH _____	MODERATE _____ LOW <u>X</u>
POTENTIAL FOR AIR EROSION:	HIGH _____	MODERATE _____ LOW <u>X</u>
OVERALL RATING:	HIGH _____	MODERATE _____ LOW <u>X</u>

DESCRIPTION open

LOCATION IN AIR PLENUM: YES X NO _____
 COMMENTS open

INSPECTOR: Charles Spear ACCREDITATION NO. IAO-21-24357
 SIGNATURE: Charles Spear DATE: 2/21/26 rm

RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING Gaston HS FLOOR MAIN
FUNCTIONAL AREA Classroom HOMOGENEOUS MATERIAL Moum mastic
TYPE OF SUSPECT MATERIAL SURFACING TSI
FLOORING CEILING WALLS OTHER X
DESCRIPTION OF MATERIAL _____

APPROXIMATE AMOUNT OF MATERIAL (SF) 10 (LF) 50 K +REINSPECTION DATA : OK inACBM TYPE: SURFACING _____ TSI _____ MISC X FLOOR _____ CEILING _____

DESCRIPTION

Moum mastic
APPROXIMATE AMOUNT OF MATERIAL (SF) _____ (LF) 50 K
FRIABLE: _____ (YES) X (NO) _____
NON-FRIABLE _____ (YES) _____ (NO) X
WARNING LABELS (YES) _____ (NO) X
CHANGE FROM INITIAL AHERA REPORT (YES) _____ (NO) -

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION _____ PHYSICAL X WATER _____ FIRE _____
EXTENT OF DAMAGE: LOCALIZED _____ DISTRIBUTED X
PERCENT OF DAMAGE: 0% _____ 1-10% X 10-25% _____ 25-100% _____
OVERALL RATING: GOOD _____ FAIR _____ POOR _____
DESCRIPTION: _____

POTENTIAL FOR DISTURBANCE:	ACCESSIBLE <u>X</u>	INACCESSIBLE _____
POTENTIAL FOR CONTACT:	HIGH _____	MODERATE _____ LOW <u>X</u>
INFLUENCE OF VIBRATION:	HIGH _____	MODERATE _____ LOW <u>X</u>
POTENTIAL FOR AIR EROSION:	HIGH _____	MODERATE _____ LOW <u>X</u>
OVERALL RATING:	HIGH _____	MODERATE _____ LOW _____

DESCRIPTION OK

LOCATION IN AIR PLENUM: YES X NO _____
COMMENTS OK in

INSPECTOR: Charles Spear ACCREDITATION NO. FR0-21-24391
SIGNATURE: Charles Sp DATE: 2/26/21 fr

RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING gaston 6/9 FLOOR MAIN
 FUNCTIONAL AREA Class 11/6/85 HOMOGENEOUS MATERIAL 9" tan pat VAS
 TYPE OF SUSPECT MATERIAL SURFACING _____ TSI _____
 FLOORING X CEILING _____ WALLS _____ OTHER _____
 DESCRIPTION OF MATERIAL 1 tan pat like
class include 8)
 APPROXIMATE AMOUNT OF MATERIAL (SF) 9" Ver (LF) _____

REINSPECTION DATA :

ACBM TYPE: SURFACING _____ TSI _____ MISC _____ FLOOR X CEILING _____

DESCRIPTION

9" tan pat like
 APPROXIMATE AMOUNT OF MATERIAL _____ (SF) 100 (LF) _____
 FRIABLE: _____ (YES) X (NO) _____
 NON-FRIABLE _____ (YES) _____ (NO) X
 WARNING LABELS _____ (YES) _____ (NO) 2
 CHANGE FROM INITIAL AHERA REPORT _____ (YES) _____ (NO) 2

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION _____ PHYSICAL X WATER _____ FIRE _____
 EXTENT OF DAMAGE: LOCALIZED _____ DISTRIBUTED X
 PERCENT OF DAMAGE: 0% _____ 1-10% X 10-25% _____ 25-100% _____
 OVERALL RATING: GOOD X FAIR _____ POOR _____
 DESCRIPTION: _____

POTENTIAL FOR DISTURBANCE:	ACCESSIBLE _____	INACCESSIBLE _____
POTENTIAL FOR CONTACT:	_____ HIGH <u>X</u>	MODERATE _____ LOW _____
INFLUENCE OF VIBRATION:	_____ HIGH _____	MODERATE _____ LOW <u>X</u>
POTENTIAL FOR AIR EROSION:	_____ HIGH _____	MODERATE _____ LOW <u>X</u>
OVERALL RATING:	_____ HIGH _____	MODERATE _____ LOW _____
DESCRIPTION <u>OK</u>		

LOCATION IN AIR PLENUM: YES X NO _____
 COMMENTS OK

INSPECTOR: Charles Spear ACCREDITATION NO. IR0-21-24390
 SIGNATURE: Charles Spear DATE: 2/26/21 per

RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING gordon bldg FLOOR Main
 FUNCTIONAL AREA AN HOMOGENEOUS MATERIAL MOULDING MASTICS
 TYPE OF SUSPECT MATERIAL SURFACING _____ TSI _____
 FLOORING _____ CEILING _____ WALLS _____ OTHER x
 DESCRIPTION OF MATERIAL _____

APPROXIMATE AMOUNT OF MATERIAL (SF) _____ (LF) 71016

REINSPECTION DATA :

ACBM TYPE: SURFACING _____ TSI _____ MISC x FLOOR _____ CEILING _____

DESCRIPTION

APPROXIMATE AMOUNT OF MATERIAL _____ (SF) _____ (LF) 71016
 FRIABLE: _____ (YES) x (NO) _____
 NON-FRIABLE _____ (YES) _____ (NO) x
 WARNING LABELS _____ (YES) _____ (NO) x
 CHANGE FROM INITIAL AHERA REPORT _____ (YES) _____ (NO) X

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION x PHYSICAL _____ WATER _____ FIRE _____
 EXTENT OF DAMAGE: LOCALIZED x DISTRIBUTED _____
 PERCENT OF DAMAGE: 0% _____ 1-10% x 10-25% _____ 25-100% _____
 OVERALL RATING: GOOD x FAIR _____ POOR _____
 DESCRIPTION: _____

POTENTIAL FOR DISTURBANCE: ACCESSIBLE x INACCESSIBLE _____
 POTENTIAL FOR CONTACT: _____ HIGH _____ MODERATE _____ LOW x
 INFLUENCE OF VIBRATION: _____ HIGH _____ MODERATE _____ LOW x
 POTENTIAL FOR AIR EROSION: _____ HIGH _____ MODERATE _____ LOW x
 OVERALL RATING: _____ HIGH _____ MODERATE _____ LOW x

DESCRIPTION: X Candidate for in-place operations and maintenance
 LOCATION IN AIR PLENUM: YES x NO _____

COMMENTS

Operations and
 Maintenance OK

INSPECTOR: Charles Spear ACCREDITATION NO. IR-19-2439A IR-21-2439A
 SIGNATURE: Charles Spear DATE: 2/20/21

RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING GASION BLS FLOOR MAIN
 FUNCTIONAL AREA offices HOMOGENEOUS MATERIAL 9" acc ceiling tiles
 TYPE OF SUSPECT MATERIAL SURFACING TSI
 FLOORING CEILING ☒ WALLS OTHER ☒
 DESCRIPTION OF MATERIAL ceiling tiles - 9" acc

APPROXIMATE AMOUNT OF MATERIAL (SF) 1200 (LF) 1200

REINSPECTION DATA :

ACBM TYPE: SURFACING TSI MISC ☒ FLOOR CEILING ☒

DESCRIPTION

9" acc tiles
 APPROXIMATE AMOUNT OF MATERIAL (SF) 1200 (LF) 1200
 FRIABLE: (YES) ☒ (NO)
 NON-FRIABLE (YES) (NO) ☒
 WARNING LABELS (YES) (NO) ☒
 CHANGE FROM INITIAL AHERA REPORT (YES) (NO) ☒

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION PHYSICAL ☒ WATER FIRE
 EXTENT OF DAMAGE: LOCALIZED DISTRIBUTED ☒
 PERCENT OF DAMAGE: 0% 1-10% ☒ 10-25% 25-100%
 OVERALL RATING: GOOD ☒ FAIR POOR
 DESCRIPTION:

POTENTIAL FOR DISTURBANCE:	ACCESSIBLE <input checked="" type="checkbox"/>	INACCESSIBLE <u> </u>
POTENTIAL FOR CONTACT:	HIGH <u> </u>	MODERATE <u> </u> LOW <input checked="" type="checkbox"/>
INFLUENCE OF VIBRATION:	HIGH <u> </u>	MODERATE <u> </u> LOW <input checked="" type="checkbox"/>
POTENTIAL FOR AIR EROSION:	HIGH <u> </u>	MODERATE <u> </u> LOW <input checked="" type="checkbox"/>
OVERALL RATING:	HIGH <u> </u>	MODERATE <u> </u> LOW <input checked="" type="checkbox"/>

DESCRIPTION offices

LOCATION IN AIR PLENUM: YES ☒ NO
 COMMENTS offices

INSPECTOR: Charles Spear ACCREDITATION NO. IR0-21-24390
 SIGNATURE: Charles Spear DATE: 2/26/21 - FR

RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING Gaston Bldg. FLOOR MAN
 FUNCTIONAL AREA offices HOMOGENEOUS MATERIAL WOODLAM mastic
 TYPE OF SUSPECT MATERIAL SURFACING _____ TSI _____
 FLOORING _____ CEILING _____ WALLS _____ OTHER x
 DESCRIPTION OF MATERIAL WOODLAM mastic

APPROXIMATE AMOUNT OF MATERIAL (SF) _____ (LF) 1K

REINSPECTION DATA :

ACBM TYPE: SURFACING _____ TSI _____ MISC Δ FLOOR _____ CEILING _____

DESCRIPTION

WOODLAM mastic
 APPROXIMATE AMOUNT OF MATERIAL (SF) _____ (LF) 1K
 FRIABLE: _____ (YES) x (NO) _____
 NON-FRIABLE _____ (YES) _____ (NO) x
 WARNING LABELS _____ (YES) _____ (NO) x
 CHANGE FROM INITIAL AHERA REPORT _____ (YES) _____ (NO) x

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION _____ PHYSICAL x WATER _____ FIRE _____
 EXTENT OF DAMAGE: LOCALIZED _____ DISTRIBUTED x
 PERCENT OF DAMAGE: 0% _____ 1-10% x 10-25% _____ 25-100% _____
 OVERALL RATING: GOOD x FAIR _____ POOR _____
 DESCRIPTION: int.

POTENTIAL FOR DISTURBANCE: ACCESSIBLE x INACCESSIBLE _____
 POTENTIAL FOR CONTACT: _____ HIGH _____ MODERATE _____ LOW x
 INFLUENCE OF VIBRATION: _____ HIGH _____ MODERATE _____ LOW x
 POTENTIAL FOR AIR EROSION: _____ HIGH _____ MODERATE _____ LOW x
 OVERALL RATING: _____ HIGH _____ MODERATE _____ LOW x
 DESCRIPTION off

LOCATION IN AIR PLENUM: YES x NO _____
 COMMENTS off

INSPECTOR: Charles Spear ACCREDITATION NO. IR20-21-2439A
 SIGNATURE: Charles Spear DATE: 2/26/21-JV

RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING 995th 1315 FLOOR MAIN
 FUNCTIONAL AREA hallway HOMOGENEOUS MATERIAL 1' ten part tiles
 TYPE OF SUSPECT MATERIAL SURFACING _____ TSI _____
 FLOORING X CEILING _____ WALLS _____ OTHER _____
 DESCRIPTION OF MATERIAL 1' ten part tiles

APPROXIMATE AMOUNT OF MATERIAL (SF) 101ct (LF) _____

REINSPECTION DATA :

ACBM TYPE: SURFACING _____ TSI _____ MISC _____ FLOOR X CEILING _____

DESCRIPTION

APPROXIMATE AMOUNT OF MATERIAL (SF) 101ct (LF) _____
 FRIABLE: _____ (YES) X (NO) _____
 NON-FRIABLE _____ (YES) _____ (NO) X
 WARNING LABELS _____ (YES) _____ (NO) X
 CHANGE FROM INITIAL AHERA REPORT _____ (YES) _____ (NO) X

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION _____ PHYSICAL X WATER _____ FIRE _____
 EXTENT OF DAMAGE: LOCALIZED _____ DISTRIBUTED X
 PERCENT OF DAMAGE: 0% _____ 1-10% X 10-25% _____ 25-100% _____
 OVERALL RATING: GOOD X FAIR _____ POOR _____
 DESCRIPTION: DEFU

POTENTIAL FOR DISTURBANCE: ACCESSIBLE X INACCESSIBLE _____
 POTENTIAL FOR CONTACT: _____ HIGH _____ MODERATE _____ LOW X
 INFLUENCE OF VIBRATION: _____ HIGH _____ MODERATE _____ LOW X
 POTENTIAL FOR AIR EROSION: _____ HIGH _____ MODERATE _____ LOW X
 OVERALL RATING: _____ HIGH _____ MODERATE _____ LOW X
 DESCRIPTION DEFU

LOCATION IN AIR PLENUM: YES X NO _____
 COMMENTS DEFU

INSPECTOR: Charles Spear ACCREDITATION NO. IR0-24-24394
 SIGNATURE: Charles Spear DATE: 2/16/21

RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING Easton, B/S FLOOR MAIN
 FUNCTIONAL AREA hallway HOMOGENEOUS MATERIAL 1' pink put filler
 TYPE OF SUSPECT MATERIAL SURFACING _____ TSI _____
 FLOORING X CEILING _____ WALLS _____ OTHER _____
 DESCRIPTION OF MATERIAL 1' pink put filler

APPROXIMATE AMOUNT OF MATERIAL (SF) 1.5 (LF) _____

REINSPECTION DATA :

ACBM TYPE: SURFACING _____ TSI _____ MISC _____ FLOOR X CEILING _____

DESCRIPTION

APPROXIMATE AMOUNT OF MATERIAL (SF) 1.5 (LF) _____
 FRIABLE: _____ (YES) X (NO) _____
 NON-FRIABLE _____ (YES) _____ (NO) X
 WARNING LABELS _____ (YES) _____ (NO) X
 CHANGE FROM INITIAL AHERA REPORT _____ (YES) _____ (NO) X

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION _____ PHYSICAL X WATER _____ FIRE _____
 EXTENT OF DAMAGE: LOCALIZED _____ DISTRIBUTED X
 PERCENT OF DAMAGE: 0% _____ 1-10% X 10-25% _____ 25-100% _____
 OVERALL RATING: GOOD X FAIR _____ POOR _____
 DESCRIPTION: _____

POTENTIAL FOR DISTURBANCE: ACCESSIBLE X INACCESSIBLE _____
 POTENTIAL FOR CONTACT: _____ HIGH _____ MODERATE _____ LOW X
 INFLUENCE OF VIBRATION: X HIGH _____ MODERATE _____ LOW _____
 POTENTIAL FOR AIR EROSION: _____ HIGH _____ MODERATE _____ LOW X
 OVERALL RATING: _____ HIGH _____ MODERATE _____ LOW X
 DESCRIPTION obm

LOCATION IN AIR PLENUM: YES X NO _____
 COMMENTS obm

INSPECTOR: Charles Spear ACCREDITATION NO. IR0-21-2439A
 SIGNATURE: Charles Spear DATE: 2/21/20 FM

RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING gastown bldg. FLOOR MAN
 FUNCTIONAL AREA halls HOMOGENEOUS MATERIAL MODULAR mastic
 TYPE OF SUSPECT MATERIAL SURFACING _____ TSI _____
 FLOORING _____ CEILING _____ WALLS _____ OTHER X
 DESCRIPTION OF MATERIAL MODULAR mastic

APPROXIMATE AMOUNT OF MATERIAL (SF) _____ (LF) 10 Kt

REINSPECTION DATA :

ACBM TYPE: SURFACING _____ TSI _____ MISC X FLOOR _____ CEILING _____

DESCRIPTION

MODULAR mastic
 APPROXIMATE AMOUNT OF MATERIAL _____ (SF) 10K (LF) _____
 FRIABLE: _____ (YES) X (NO) _____
 NON-FRIABLE _____ (YES) _____ (NO) X
 WARNING LABELS _____ (YES) _____ (NO) X
 CHANGE FROM INITIAL AHERA REPORT _____ (YES) _____ (NO) X

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION _____ PHYSICAL X WATER _____ FIRE _____
 EXTENT OF DAMAGE: LOCALIZED _____ DISTRIBUTED X
 PERCENT OF DAMAGE: 0% _____ 1-10% X 10-25% _____ 25-100% _____
 OVERALL RATING: GOOD X FAIR _____ POOR _____
 DESCRIPTION: 12 ft

POTENTIAL FOR DISTURBANCE: ACCESSIBLE X INACCESSIBLE _____
 POTENTIAL FOR CONTACT: _____ HIGH _____ MODERATE _____ LOW X
 INFLUENCE OF VIBRATION: _____ HIGH _____ MODERATE _____ LOW X
 POTENTIAL FOR AIR EROSION: _____ HIGH _____ MODERATE _____ LOW X
 OVERALL RATING: _____ HIGH _____ MODERATE _____ LOW X
 DESCRIPTION OPEN

LOCATION IN AIR PLENUM: YES X NO _____
 COMMENTS OPEN

INSPECTOR: Charles Spear ACCREDITATION NO. IR0-21-2439A
 SIGNATURE: Charles Spear DATE: 2/24/21

RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING gastun blk FLOOR Main
FUNCTIONAL AREA hall HOMOGENEOUS MATERIAL acc files
TYPE OF SUSPECT MATERIAL SURFACING TSI
FLOORING CEILING X WALLS OTHER X
DESCRIPTION OF MATERIAL acc ceiling files & on walls

APPROXIMATE AMOUNT OF MATERIAL (SF) 21016 (LF) _____

REINSPECTION DATA :

ACBM TYPE: SURFACING _____ TSI _____ MISC X FLOOR _____ CEILING X

DESCRIPTION

acc ceiling files
APPROXIMATE AMOUNT OF MATERIAL (SF) 21016 (LF) _____
FRIABLE: _____ (YES) X (NO) _____
NON-FRIABLE _____ (YES) _____ (NO) X
WARNING LABELS _____ (YES) _____ (NO) X
CHANGE FROM INITIAL AHERA REPORT _____ (YES) _____ (NO) X

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION _____ PHYSICAL X WATER _____ FIRE _____
EXTENT OF DAMAGE: LOCALIZED _____ DISTRIBUTED X
PERCENT OF DAMAGE: 0% _____ 1-10% X 10-25% _____ 25-100% _____
OVERALL RATING: GOOD X FAIR _____ POOR _____
DESCRIPTION: contact

POTENTIAL FOR DISTURBANCE: ACCESSIBLE X INACCESSIBLE _____
POTENTIAL FOR CONTACT: _____ HIGH _____ MODERATE _____ LOW X
INFLUENCE OF VIBRATION: _____ HIGH _____ MODERATE _____ LOW X
POTENTIAL FOR AIR EROSION: _____ HIGH _____ MODERATE _____ LOW X
OVERALL RATING: _____ HIGH _____ MODERATE _____ LOW X
DESCRIPTION OKW

LOCATION IN AIR PLENUM: YES X NO _____
COMMENTS OKW

INSPECTOR: Charles Spear ACCREDITATION NO. IR0-21-2439A
SIGNATURE: Charles Spear DATE: 2/26/11-PW

RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING gaston o/s FLOOR MAIN
 FUNCTIONAL AREA throughout HOMOGENEOUS MATERIAL walls / textures
 TYPE OF SUSPECT MATERIAL SURFACING X TSI _____
 FLOORING _____ CEILING _____ WALLS _____ OTHER _____
 DESCRIPTION OF MATERIAL wall textures

APPROXIMATE AMOUNT OF MATERIAL (SF) 50 K+ (LF) _____

REINSPECTION DATA :

ACBM TYPE: SURFACING X TSI _____ MISC _____ FLOOR _____ CEILING _____

DESCRIPTION

wall textures
 APPROXIMATE AMOUNT OF MATERIAL _____ (SF) 50 K+ (LF) _____
 FRIABLE: _____ (YES) ✓ (NO) _____
 NON-FRIABLE _____ (YES) _____ (NO) ✓
 WARNING LABELS _____ (YES) _____ (NO) ✓
 CHANGE FROM INITIAL AHERA REPORT _____ (YES) _____ (NO) ✓

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION _____ PHYSICAL X WATER _____ FIRE _____
 EXTENT OF DAMAGE: LOCALIZED _____ DISTRIBUTED X
 PERCENT OF DAMAGE: 0% _____ 1-10% ✓ 10-25% _____ 25-100% _____
 OVERALL RATING: GOOD X FAIR _____ POOR _____
 DESCRIPTION: 1. intact

POTENTIAL FOR DISTURBANCE:	ACCESSIBLE <u>X</u>	INACCESSIBLE _____
POTENTIAL FOR CONTACT:	_____ HIGH _____	MODERATE _____ LOW <u>✓</u>
INFLUENCE OF VIBRATION:	_____ HIGH _____	MODERATE _____ LOW <u>X</u>
POTENTIAL FOR AIR EROSION:	_____ HIGH _____	MODERATE _____ LOW <u>✓</u>
OVERALL RATING:	_____ HIGH _____	MODERATE _____ LOW <u>✓</u>
DESCRIPTION	<u>Open</u>	

LOCATION IN AIR PLENUM: YES ✓ NO _____
 COMMENTS Open

INSPECTOR: Charles Spear ACCREDITATION NO. FED-21-2439A
 SIGNATURE: Charles Spear DATE: 2/26/21

RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING Gaston Pl. Bldg FLOOR MAIN
 FUNCTIONAL AREA Restroom HOMOGENEOUS MATERIAL 1' thin port and
 TYPE OF SUSPECT MATERIAL SURFACING _____ TSI _____
 FLOORING ☒ CEILING _____ WALLS _____ OTHER _____
 DESCRIPTION OF MATERIAL _____

APPROXIMATE AMOUNT OF MATERIAL (SF) 125 (LF) _____

REINSPECTION DATA :

ACBM TYPE: SURFACING _____ TSI _____ MISC _____ FLOOR ☒ CEILING _____

DESCRIPTION

APPROXIMATE AMOUNT OF MATERIAL (SF) 125 (LF) _____
 FRIABLE: _____ (YES) ☒ (NO) _____
 NON-FRIABLE _____ (YES) _____ (NO) ☒
 WARNING LABELS _____ (YES) _____ (NO) ☒
 CHANGE FROM INITIAL AHERA REPORT _____ (YES) _____ (NO) ☒

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION _____ PHYSICAL ☒ WATER _____ FIRE _____
 EXTENT OF DAMAGE: LOCALIZED _____ DISTRIBUTED ☒
 PERCENT OF DAMAGE: 0% _____ 1-10% ☒ 10-25% _____ 25-100% _____
 OVERALL RATING: GOOD ☒ FAIR _____ POOR _____
 DESCRIPTION: _____

POTENTIAL FOR DISTURBANCE:	ACCESSIBLE <input checked="" type="checkbox"/>	INACCESSIBLE
POTENTIAL FOR CONTACT:	HIGH _____	MODERATE _____ LOW <input checked="" type="checkbox"/>
INFLUENCE OF VIBRATION:	HIGH _____	MODERATE _____ LOW <input checked="" type="checkbox"/>
POTENTIAL FOR AIR EROSION:	HIGH _____	MODERATE _____ LOW <input checked="" type="checkbox"/>
OVERALL RATING:	HIGH _____	MODERATE _____ LOW <input checked="" type="checkbox"/>

DESCRIPTION 0 & M

LOCATION IN AIR PLENUM: YES ☒ NO _____
 COMMENTS 0 & M

INSPECTOR: Charles Spent ACCREDITATION NO. FR0-21-24398
 SIGNATURE: Charles Sp DATE: 2/26/24 -m

RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING gaston pls FLOOR man
 FUNCTIONAL AREA restroom HOMOGENEOUS MATERIAL 1' acc tiles
 TYPE OF SUSPECT MATERIAL SURFACING _____ TSI _____
 FLOORING _____ CEILING X WALLS _____ OTHER _____
 DESCRIPTION OF MATERIAL acc. tiles

APPROXIMATE AMOUNT OF MATERIAL (SF) 14 sq (LF) _____

REINSPECTION DATA :

ACBM TYPE: SURFACING _____ TSI _____ MISC X FLOOR _____ CEILING X

DESCRIPTION 1' acc ceiling tiles

APPROXIMATE AMOUNT OF MATERIAL (SF) 14 sq (LF) _____
 FRIABLE: (YES) X (NO) _____
 NON-FRIABLE (YES) _____ (NO) X
 WARNING LABELS (YES) _____ (NO) X
 CHANGE FROM INITIAL AHERA REPORT (YES) _____ (NO) 1

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION _____ PHYSICAL Y WATER _____ FIRE _____
 EXTENT OF DAMAGE: LOCALIZED _____ DISTRIBUTED X
 PERCENT OF DAMAGE: 0% _____ 1-10% X 10-25% _____ 25-100% _____
 OVERALL RATING: GOOD X FAIR _____ POOR _____
 DESCRIPTION: _____

POTENTIAL FOR DISTURBANCE:	ACCESSIBLE <u>X</u>	INACCESSIBLE
POTENTIAL FOR CONTACT:	HIGH _____	MODERATE _____ LOW <u>X</u>
INFLUENCE OF VIBRATION:	HIGH _____	MODERATE _____ LOW <u>X</u>
POTENTIAL FOR AIR EROSION:	HIGH _____	MODERATE _____ LOW <u>X</u>
OVERALL RATING:	HIGH _____	MODERATE _____ LOW <u>X</u>
DESCRIPTION <u>Obv</u>		

LOCATION IN AIR PLENUM: YES _____ NO _____
 COMMENTS Obv

INSPECTOR: Charles Spear ACCREDITATION NO. FAO-24-24397
 SIGNATURE: Charles Spear DATE: 2/26/21 - 12

RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING Commons FLOOR M.O.W.
 FUNCTIONAL AREA Floor HOMOGENEOUS MATERIAL Vinyl Floor
 TYPE OF SUSPECT MATERIAL SURFACING TSI
 FLOORING X CEILING WALLS OTHER black/bm vinyl
 DESCRIPTION OF MATERIAL

APPROXIMATE AMOUNT OF MATERIAL (SF) 1000 (LF) 1000

REINSPECTION DATA :

ACBM TYPE: SURFACING TSI MISC FLOOR X CEILING CEILING

DESCRIPTION

APPROXIMATE AMOUNT OF MATERIAL (SF) 1000 (LF) 1000
 FRIABLE: (YES) X (NO) _____
 NON-FRIABLE (YES) _____ (NO) X
 WARNING LABELS (YES) _____ (NO) X
 CHANGE FROM INITIAL AHERA REPORT (YES) _____ (NO) X

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION PHYSICAL X WATER _____ FIRE _____
 EXTENT OF DAMAGE: LOCALIZED DISTRIBUTED X
 PERCENT OF DAMAGE: 0% 1-10% X 10-25% 25-100% _____
 OVERALL RATING: GOOD FAIR _____ POOR _____
 DESCRIPTION: _____

POTENTIAL FOR DISTURBANCE:	ACCESSIBLE <u>_____</u>	INACCESSIBLE <u>_____</u>
POTENTIAL FOR CONTACT:	<u>X</u> HIGH <u>_____</u>	MODERATE <u>_____</u> LOW <u>_____</u>
INFLUENCE OF VIBRATION:	<u>_____</u> HIGH <u>_____</u>	MODERATE <u>_____</u> LOW <u>X</u>
POTENTIAL FOR AIR EROSION:	<u>_____</u> HIGH <u>_____</u>	MODERATE <u>_____</u> LOW <u>X</u>
OVERALL RATING:	<u>_____</u> HIGH <u>_____</u>	MODERATE <u>_____</u> LOW <u>_____</u>
DESCRIPTION <u>DBM</u>		

LOCATION IN AIR PLENUM: YES X NO _____
 COMMENTS DBM

INSPECTOR: Charles Spear ACCREDITATION NO. L20-21-24392
 SIGNATURE: Charles Spear DATE: 2/26/21

RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING Common FLOOR MAIN
 FUNCTIONAL AREA Gymnasium HOMOGENEOUS MATERIAL tan vinyl tile
 TYPE OF SUSPECT MATERIAL SURFACING TSI
 FLOORING X CEILING _____ WALLS _____ OTHER _____
 DESCRIPTION OF MATERIAL 10K - tan vinyl tile

APPROXIMATE AMOUNT OF MATERIAL (SF) 10K (LF) _____

REINSPECTION DATA :

ACBM TYPE: SURFACING _____ TSI _____ MISC _____ FLOOR X CEILING _____

DESCRIPTION

APPROXIMATE AMOUNT OF MATERIAL (SF) 10K (LF) _____
 FRIABLE: _____ (YES) X (NO) _____
 NON-FRIABLE _____ (YES) _____ (NO) X
 WARNING LABELS _____ (YES) _____ (NO) X
 CHANGE FROM INITIAL AHERA REPORT _____ (YES) _____ (NO) X

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION _____ PHYSICAL X WATER _____ FIRE _____
 EXTENT OF DAMAGE: LOCALIZED _____ DISTRIBUTED X
 PERCENT OF DAMAGE: 0% _____ 1-10% X 10-25% _____ 25-100% _____
 OVERALL RATING: GOOD X FAIR _____ POOR _____
 DESCRIPTION: intact - new

POTENTIAL FOR DISTURBANCE: ACCESSIBLE X INACCESSIBLE _____
 POTENTIAL FOR CONTACT: _____ HIGH _____ MODERATE X LOW _____
 INFLUENCE OF VIBRATION: X HIGH _____ MODERATE _____ LOW _____
 POTENTIAL FOR AIR EROSION: _____ HIGH _____ MODERATE _____ LOW X
 OVERALL RATING: _____ HIGH _____ MODERATE _____ LOW X
 DESCRIPTION off

LOCATION IN AIR PLENUM: YES X NO _____
 COMMENTS Off

INSPECTOR: Charles Spear ACCREDITATION NO. IR0-21-24397
 SIGNATURE: Charles Spear DATE: 2/26/21

RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING Commons FLOOR Main
FUNCTIONAL AREA Walls HOMOGENEOUS MATERIAL plaster-text
TYPE OF SUSPECT MATERIAL SURFACING TSI
FLOORING CEILING WALLS X OTHER
DESCRIPTION OF MATERIAL knave - SR

APPROXIMATE AMOUNT OF MATERIAL (SF) 1014 (LF) _____

REINSPECTION DATA :

ACBM TYPE: SURFACING _____ TSI _____ MISC X FLOOR _____ CEILING _____

DESCRIPTION

sheetrock 1
APPROXIMATE AMOUNT OF MATERIAL (SF) 1014 (LF) _____
FRIABLE: (YES) X (NO) _____
NON-FRIABLE (YES) _____ (NO) X
WARNING LABELS (YES) _____ (NO) X
CHANGE FROM INITIAL AHERA REPORT (YES) _____ (NO) X

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION X PHYSICAL _____ WATER _____ FIRE _____
EXTENT OF DAMAGE: LOCALIZED X DISTRIBUTED _____
PERCENT OF DAMAGE: 0% _____ 1-10% X 10-25% _____ 25-100% _____
OVERALL RATING: GOOD X FAIR _____ POOR _____
DESCRIPTION: OFM

POTENTIAL FOR DISTURBANCE: ACCESSIBLE X INACCESSIBLE _____
POTENTIAL FOR CONTACT: HIGH _____ MODERATE _____ LOW X
INFLUENCE OF VIBRATION: HIGH _____ MODERATE _____ LOW X
POTENTIAL FOR AIR EROSION: HIGH _____ MODERATE _____ LOW X
OVERALL RATING: HIGH _____ MODERATE _____ LOW X
DESCRIPTION OFM

LOCATION IN AIR PLENUM: YES X NO _____
COMMENTS OFMINSPECTOR: Charles Spier
SIGNATURE: Charles SpierACCREDITATION NO. IPD-21-2439A
DATE: 2/26/21

APPENDIX 3.0

REGULATIONS

RESUME

CHARLES ARTHUR SPEAR

**CENTER FOR ENVIRONMENTAL RESEARCH
& TECHNOLOGY RADON TRAINING**

**CERTIFIED ENVIRONMENTAL CONSULTANT (CEC)
ENVIRONMENTAL ASSESSMENT ASSOCIATION**

**REGISTERED ENVIRONMENTAL ASSESSOR
(Former) REA - 01241**

AHERA INSPECTOR (EPA CERTIFICATION NO. IR-20-2439A

**CERTIFIED ENVIRONMENTAL INSPECTOR
CEI - 10364**

Professional Background

Charles A. Spear, President and founder of Environmental Inspection Services has over 30 years technical experience ranging from facility and school district radon testing to site remediation. Technical employment included food technologist to hazardous waste site remediation at Federal SUPERFUND sites from California to Maryland. Mr. Spear has successfully performed over 3,000 Phase One, Phase Two, and Phase Three Environmental Site Assessment inspections and multiple radon inspections and surveys on properties from California to Alaska and east to Maryland.

Mr. Spear has managed such projects as spilled mustard gas and organophosphate demilitarization and remediation as a decontamination sergeant of the U.S. Army Chemical Corps Technical Escort Unit Drill & Transfer Unit at Umatilla Army Depot and removal of leaking solvent underground storage tanks in California and Oregon. Additional experience included supervision as a USARMY NBC Specialist of focused remediation at the Federal Superfund site known as Aberdeen Proving Grounds, Maryland (Michaelsville Landfill). EIS does not conduct or perform geological work. Geologic work is referred to a state registered geologist.

Specifically, Mr. Spear has worked with clients such as: numerous school districts, Housing & Urban Development, the International Fabric Care Industry (IFI), the U.S. Environmental Protection Agency, The U.S. Department of Defense, The Oregon Department of Environmental Quality (ODEQ), The Oregon Department of Forestry, INTEL, Sun Microsystems, IBM, Rohm & Haas, General Electric, AT&T, Texaco, Unocal, BP, Lockheed Missile and Space Center, FMC Corporation, Oregon Department of Fish & Wildlife, Washington Department of Fish & Wildlife, City of Beaverton, City of Hillsboro, City of Corvallis, Housing Authority of Portland, Northwest Oregon Housing Authority, Washington County Department of Housing, Housing & Urban Development, numerous lenders and mortgage companies, many private development and site remedial site projects, and many attorneys and investors.

Mr. Spear managed complex solvent tank farm removals at Xidex Corporation in Sunnyvale, California and was the site cleanup manager at the Rose City Plating Site currently developed as the Oregon Convention Center. Mr. Spear is a certified hazardous waste professional who has coupled military experience as a Nuclear, Biological and Chemical Specialist (U.S. Army MOS 54E20) with experience as a professional industrial and process research engineer in both the corrugated paper and petroleum industries.

Mr. Spear has managed food industry quality control as an inplant food technologist and prepared cost reduction programs as a corrugated boxboard industrial engineer in Dallas, Texas. He is currently registered with the states of California, Washington, and Oregon and is an active member of the national respected Environmental Assessment Association. Due diligence projects have been performed throughout the United States from Fairbanks, Alaska to San Diego, California.

Professional experience includes the following:

Professional Experience

- * Dry Cleaner Inspections
- * Environmental Consultation
- * Waste Reduction Audits
- * Regulatory Compliance Audits
- * Drum Yard Clearances
- * Tank Farm Removals/Replacements
- * Lab Packaging & Supervision
- * Environmental Site Assessments
- * Superfund Site Remediation
- * Hazardous Waste site Project Design & Management
- * Habitat/Wetlands Restoration
- * AHERA asbestos inspections for school districts
- * Landfill Remediation
- * Agricultural assessments
- * Indoor air quality inspections

Professional Employment/Consultation

- * C.F.S. Continental Coffee, Inc., Food technologist, Chicago, Illinois
- * Holiday Industries, Research Engineer, Grand Prairie, Texas
- * Alton Packaging Corporation, Industrial Engineer, Dallas, Texas
- * U.S. Army Chemical Corps., Nuclear, Biological, Chemical Specialist - Special assignment - Umatilla Army Depot (DATS)
- * Oregon and permanent assignment U.S. Army Chemical Corps. Technical Escort Unit in Edgewood, Maryland
- * Rollins Environmental Services, Remedial Project Manager
- * Crown Environmental Services, Technical Director, Redmond, California
- * Dames & Moore, Remedial design Engineer, Portland, Oregon
- * Pegasus Environmental Management Services, Director of Technical Services
- * Pacific Tank & Construction, Manager of Estimation, Portland, Oregon
- * Enviro-Logic Inc., Director of Environmental Site Assessment Division
- * Environmental Inspection Services Founder / President

Professional Education

- * Environmental Research & Technology radon training
- * American Standard for Testing & Materials ASTM E1527-13 Training
- * Bachelor of Science, Chemistry, Northeastern Illinois University, 1978
- * U.S. Army Chemical School, Ft. McClellan, Alabama, 1983
- * U.S. Army Technical Escort Unit, Accident / Incident Response Training Center 1983
- * Registered Environmental Assessor REA - 01241 (Former classification)
- * Certified environmental Inspector CEI - 10364
- * AHERA Certified Asbestos Inspector IR-19-2439A
- * ODEQ Soil Matrix Assessor & UST Decommission Supervisor ID No. 10305
- * Washington DOE Registered Environmental Assessor
- * Wetland Specialist - Training Wetlands Institute 1997
- * EPA / HUD Lead-Based Paint (LBP) Certified Inspector & Risk Assessor

Additional Education

- * Joint Military Material Packaging & Transportation
- * Asbestos Abatement Seminar attendance 1987
- * Thin Layer Chromatography, 1989
- * Oregon Registered Underground storage Tank Supervisor, 1998
- * Oregon Registered Soil Matrix Assessor, 1998
- * Washington Registered Assessor, 1991
- * Washington Registered Underground Storage Tank Supervisor, 1991
- * Wetland Training Institute Delineation Course Study University of Portland 1997
- * 40-Hour HAZMAT Certified
- * AHERA-Certified Inspector

Special Skills

- * Facility Environmental Compliance Audits
- * ASTM standard Environmental Site Assessments
- * Computer Programming
- * Organic surfactant chemical synthesis and analysis
- * Hazardous Waste Site remediation/ estimating/ standards development
- * Design of filtration systems, batch and continuous process optimization studies
- * QA/QC Procedures
- * SUPERFUND Site Management
- * Industrial/ Research Engineering
- * Hazardous Waste Site Remediation/ Consultation
- * Wetlands Delineation and Habitat Restoration

Certification

- * U.S. Army MOS 54E20 - U.S. Army Chemical Corps.
- * International Fire Code Institute (IFCI) Certified UST Supervisor
- * International Fire Code Institute (IFCI) Certified Soil Matrix Assessor
- * Certified Hazardous Waste Manager
- * 40-hour OSHA Training
- * 40-hour OSHA Supervisor Training
- * Registered Environmental Assessor (DOE)
- * DEQ Registered UST Supervisor
- * DEQ Registered Soil Matrix Assessor
- * Resolution Trust Corporation (RTC) approved Environmental Assessor
- * California Registered Environmental Assessor (REA-01241)- program discontinued
- * Department of Ecology (DOE) Registered Environmental Assessor
- * Environmental Assessment Association, Certified Environmental Inspector & Transaction Specialist (CEI-10364)
- * Environmental Assessment Association, Certified Environmental Consultant (CEC)
- * AHERA Certified Asbestos Inspector
- * Wetland Delineator Graduate Wetland Training Institute, University of Portland 1997
- * EPA / HUD LBP Inspector & Risk Assessor
- * ASTM Training class, May, 2004